

Assembly Instruction


IMS CONNECTOR SYSTEMS GmbH
 Obere Hauptstrasse 30
 D-79843 Löffingen
 Postfach 1141
 D-79840 Löffingen

Tel (+49) 7654 901-0
 Fax (+49) 7654 901-199
 Net: www.imscs.com
 E-mail: sales@imscs.com

Number: M-255
 Description: Cable jack


Date: 25.04.13
 Signature: Á. Varga
 Page: 1 of 1

Using parts:



Crimp tool: AGK-4436
 Assembly aid: AGK-4443


1.) Slide the crimp ferrule and the heatsink tube (opt.) onto the cable.



2.) Crimp or solder the center contact.



3.) Fan the braid and slide the cable into cable plug until stop in the assembly aid.



4.) Slide the ferrule over the braid, and crimp the ferrule.

